





Left: I recently acquired a genuine RACAL VFO2 Test Set.

Below: The underside of VFO2 seen through the bottom of the test set. Like the PSU, this sub-assembly had likely been refurbished back in the 1970s judging by the style of capacitors used. However, all tubular capacitors and carbon resistors have now been replaced with modern components.



Left: the top and bottom capacitors in this photograph are safety mods. The top one serves to isolate the main tuning capacitor from HT+, whilst the bottom capacitor serves to isolate one of the rear panel connectors from HT+.